



NESOUŠÁ REDUKCE PR

Označení	d	d ₁	L _s
PR 100/125	125	110,5	82
PR 125/150	160	125,5	108
PR 100/125	140	110,5	115
PR 125/150	160	140,6	120
PR 150/200	200	160,6	164



ŠACHTOVÁ PŘECHODKA PŠV

Označení	d	d ₁	L	e
PŠV 125	149,0	125,4	200	3,1
PŠV 150	188,5	160,6	200	3,9
PŠV 200	230,0	200,7	200	4,9
PŠV 300	345,0	316,1	200	7,7
PŠV 400	430,0	401,3	200	9,8



PŘESUVKA PU

Označení	d	d ₁	e
PU 100	150	110,5	3,0
PU 125	150	125,5	3,1
PU 125	170	140,6	3,6
PU 150	198	160,6	4,0
PU 200	200	200,7	4,9
PU 300	328	316,1	7,7
PU 400	378	401,3	9,8

